

Ref.	Common Name	Variety	Location	Protected	Maturity	No. Stems	Life Expectancy	Height	Crown width (m)	Structural Condition	Biological Condition	Pathogen Significance	Consequence of Whole tree failure	Inspect Period	Survey Notes	Size of Part	Likelihood of impact	Tree Failure Potential	Probability
T001	Norway maple		Edge of site near property on Underdale Road	N/A	Mature	1	EL (40+ Years)	15	10	Good	Good	None Present	Major	2 Years	Crown over adjacent property has been pruned back. Some low branch tips over the edge of the car park.	None	Not Assessed	Not Assessed	
T002	Cherry		Edge of grass next to car park	N/A	Mature	1	M (10-20 Years)	10	10	Good	Good	None Present	Moderate	2 Years	Relatively high crown clearance. Damage of shallow surface rooting by mowers.	None	Not Assessed	Not Assessed	
T003	Norway maple		Edge of site near property on Underdale Road	N/A	Mature	1	EL (40+ Years)	15	10	Good	Good	None Present	Major	2 Years	Crown over adjacent property has been pruned back and trees previously felled leaving gap in the crown.	None	Not Assessed	Not Assessed	
G004	Sycamore x2 Damson x2 Scots pine		Close growing group of trees located close to the boundary with properties on Underdale Road.	N/A	Mature	5	EL (40+ Years)	20	10	Good	Good	None Present	Major	2 Years	One Sycamore has been previously topped at 8m . Crown has recovered, with a dense arrangement of stems.	None	Not Assessed	Not Assessed	
G005	Pedunculate oak Broad-leaved lime Weeping willow		Dense line of 3 trees with stems within 1m of the boundary.	N/A	Semi Mature	3	EL (40+ Years)	15	10	Good	Good	None Present	Moderate	2 Years	Lime has been heavily pruned by adjacent property recently, but is a poorly formed tree. Weeping Willow has a stem lean into the site with a resulting crown biased away from the adjacent property.	None	Not Assessed	Not Assessed	
G006	Mixed species		Dense group between path to the Weir and residential properties.	N/A	Mature	1	EL (40+ Years)	20	10	Good	Good	None Present	Moderate	2 Years	Much of group has young suckering trees. Very low levels of access within the group	None	Not Assessed	Not Assessed	
T007	Sycamore		Edge of long wooded copse next to path to weir	N/A	Semi Mature	1	L (21-40 Years)	20	10	Fair	Fair	None Present	Moderate	2 Years	Crown appears thin and heavy ivy coverage on main stem and in the crown impedes inspection	None	Not Assessed	Not Assessed	
G008	White poplar x3 Common ash Red oak		L shaped group edge of shallow bank above weir area.	N/A	Mature	5	EL (40+ Years)	20	15	Fair	Good	None Present	Moderate	2 Years	Much ivy present on trees towards the weir, impeding inspection. Ash trees in good health. Some White Poplar trees have collapsed in the past	None	Not Assessed	Not Assessed	

Ref.	Common Name	Variety	Location	Protected	Maturity	No. Stems	Life Expectancy	Height	Crown width (m)	Structural Condition	Biological Condition	Pathogen Significance	Consequence of Whole tree failure	Inspect Period	Survey Notes	Size of Part	Likelihood of impact	Tree Failure Potential	Probability
G009	Cherry Sycamore Common ash Red oak Field maple Italian alder Scots pine		Long arching group centrally located, bordering the play area	N/A	Semi Mature	7	EL (40+ Years)	15	10	Good	Good	None Present	Major	2 Years	Good mixed grouping. Some trees are multi-stemmed. Much of area has low levels of or no access, but there are distinct cut through paths. Ash trees appear reasonable in health. Dead branches in group are over low risk areas. Ivy on trees barely impedes inspection, with the habitat benefit being significant. One dead tree is close to one of the cut through paths.	None	Not Assessed	Not Assessed	
G010	Mixed species		Circular group near play area.	N/A		1				Good	Good	Minor Fungal/ Pathogen Infection	Major	2 Years	One centrally located Ash has significant infection from Chalara Ash dieback disease. Large Field Maple closest to the play area is Multi-stemmed from the base with tight stem unions. Previously a large stem has split and failed but the remaning tree appears generally robust. Tight stem unions appear stable.	Medium (150-450mm)	Minor	Possible (1-5 years)	8
T011	Weeping willow		On river side next to end of salmon run	N/A	Over Mature	1	M (10-20 Years)	10	15	Fair	Good	None Present	Moderate	2 Years	Has suffered large limb failure in recent past. Owing to location, cannot inspect tree base.	None	Not Assessed	Not Assessed	
T012	Common ash		On river side 13m from end of salmon run	N/A	Over Mature	1	M (10-20 Years)	20	15	Fair	Good	None Present	Moderate	2 Years	In reasonable health. Has suffered large limb failure in recent past over river and also there are two partially torn limb over the river. No risk.	None	Not Assessed	Not Assessed	
T013	White willow		8m from rivers edge	N/A	Mature	5	L (21-40 Years)	20	10	Fair	Good	None Present	Moderate	2 Years	Ivy on stems does impede inspection, with 2 stems heavily biased towards river, the risk is relatively low as biased area is unused. Habitat value is important.	None	Not Assessed	Not Assessed	

Ref.	Common Name	Variety	Location	Protected	Maturity	No. Stems	Life Expectancy	Height	Crown width (m)	Structural Condition	Biological Condition	Pathogen Significance	Consequence of Whole tree failure	Inspect Period	Survey Notes	Size of Part	Likelihood of impact	Tree Failure Potential	Probability
T014	White willow		12m from rivers edge, next to path.	N/A	Mature	5	L (21-40 Years)	20	10	Fair	Good	None Present	Moderate	2 Years	Some Phellinus fungal fruiting bodies at the base of a few pollarded stems. Clear woodpecker hole at 3m on these stems and strong regrowth. Other is really tall and dominant with no visible decay evident.	None	Not Assessed	Not Assessed	
T015	White willow		10m from rivers edge	N/A	Mature	3	L (21-40 Years)	5	10	Fair	Good	None Present	Minor	2 Years	Pollarded at 3m, strong regrowth.	None	Not Assessed	Not Assessed	
T016	Common ash		On the waters edge	N/A	Mature	2	M (10-20 Years)	21	10	Good	Good	None Present	Moderate	2 Years	Stems heavily biased into river, tree is in reasonable health.	None	Not Assessed	Not Assessed	
T017	White willow		4m from rivers edge	N/A	Mature	3	L (21-40 Years)	5	10	Fair	Good	None Present	Minor	2 Years	Pollarded at 3m, strong regrowth.	None	Not Assessed	Not Assessed	
T018	Field maple		Centre of lower grassed area near river	N/A	Semi Mature	2	EL (40+ Years)	10	5	Good	Good	None Present	Minor	2 Years	With adjacent Willow trees pollarded this tree has a chance to grow well.	None	Not Assessed	Not Assessed	
G019	Mixed species		Shrubs and trees near path in lower grassed area by the river	N/A	Semi Mature	1	M (10-20 Years)	15	5	Good	Fair	None Present	Moderate	2 Years		None	Not Assessed	Not Assessed	
T020	White willow		8m from rivers edge	N/A	Mature	8	L (21-40 Years)	20	10	Poor	Good	Significant Fungal/ Pathogen Infection	Moderate	2 Years	Has bird box on one stem, attached with wire. At least 4 stems have phellinus fungal fruiting bodies present. Stems are slowly subsiding as demonstrated by reactive stem growth.. Tree is considered to be at a higher risk of failure	Medium (150-450mm)	Moderate	Possible (1-5 years)	12
G021	Common ash Weeping willow		Group between river edge path and lower grassed area	N/A	Mature	2	L (21-40 Years)	20	10	Good	Good	None Present	Major	2 Years	One weeping willow has been pollarded at 3m following storm damage. One Pine stem snapped at 4m. Both Ash are in good health	None	Not Assessed	Not Assessed	
T022	Crack willow		Waters edge in line with bench	N/A	Over Mature	1	M (10-20 Years)	20	15	Fair	Good	None Present	Major	2 Years	Leaning heavily into the river, considered likely to fail over time, but nothing imminent identified	Large (450-900mm)	Minor	Possible (1-5 years)	12
G023	Scots pine x5 Weeping willow Red oak Rowan x5		Group between lower grassed area and river	N/A	Mature	12	L (21-40 Years)	15	10	Good	Good	None Present	Major	2 Years	All the Scots Pine have very heavy ivy coverage on the stems.	None	Not Assessed	Not Assessed	
T024	Weeping willow		4m from rivers edge, opposite bench	N/A	Mature	1	L (21-40 Years)	10	10	Good	Good	None Present	Major	2 Years	Tree has bat box installed at 3.5m	None	Not Assessed	Not Assessed	

Ref.	Common Name	Variety	Location	Protected	Maturity	No. Stems	Life Expectancy	Height	Crown width (m)	Structural Condition	Biological Condition	Pathogen Significance	Consequence of Whole tree failure	Inspect Period	Survey Notes	Size of Part	Likelihood of impact	Tree Failure Potential	Probability
G025	Mixed species		Group near footbridge, between lower grassed area and the river	N/A	Mature	1	L (21-40 Years)	20	10	Fair	Good	None Present	Major	1 Year	One large Grey Poplar has large subsiding limbs, one notably over the footpath next to the river. Heavy ivy coverage on the three Poplars impedes stem inspection. One Weeping Willow has part collapsed into the river	None	Not Assessed	Not Assessed	
G026	Mixed species		Group next to footbridge and river	N/A	Semi Mature	1	L (21-40 Years)	15	10	Good	Good	None Present	Moderate	2 Years	Ons small dying tree in centre of group, considered low risk.	None	Not Assessed	Not Assessed	
G027	Mixed species		Long group along top of shallow separating upper and lower sections of open space.	N/A	Mature	1	M (10-20 Years)	21	15	Good	Good	None Present	Major	1 Year	Numerous large Grey Poplars with over extended limbs and stems. Much evidence of limb failure in recent years. Individual trees requiring work identified separately	None	Not Assessed	Not Assessed	
T028	Balsam poplar		Main Park edge of group, leaning smaller tree.	N/A	Semi Mature	1	M (10-20 Years)	10	5	Poor	Good	None Present	Moderate	2 Years	Leaning heavily over open grassed area. Outer extremity section has already part failed.	Medium (150-450mm)	Minor	Likely (3+ months - 1 year)	12
T029	White poplar		In long group on shallow bank opposite picnic bench.	N/A	Over Mature	2	M (10-20 Years)	21	15	Poor	Good	None Present	Major	2 Years	Broad spreading crown with many subsiding limbs and much evidence of past limb failure. Main stem heavily covered in ivy. It is considered that large over-extended limbs will continue to fail from this tree	Medium (150-450mm)	Moderate	Likely (3+ months - 1 year)	18
T030	Balsam poplar		Facing lower grassed area of park.	N/A	Semi Mature	1	M (10-20 Years)	10	5	Poor	Good	None Present	Moderate	2 Years	Leaning heavily over informal path with no reactive growth. Considered highly likely to fail on to path.	Large (450-900mm)	Minor	Likely (3+ months - 1 year)	18
T031	White poplar		In long group on shallow bank almost opposite picnic bench.	N/A	Over Mature	2	M (10-20 Years)	21	15	Poor	Good	None Present	Major	2 Years	Reasonable crown, has a lateral limb growing above leaning Poplar that is becoming vulnerable to failure, growing out over lower grassed area.	Medium (150-450mm)	Moderate	Likely (3+ months - 1 year)	18
T032	White poplar		In long group on shallow bank	N/A	Over Mature	4	M (10-20 Years)	21	15	Very Poor	Good	None Present	Major	2 Years	Stems are splitting apart at the base. Tree will require at the very least heavy pollarding Tree is in the process of failing and has been that way for at least one growing season.	Large (450-900mm)	Moderate	Likely (3+ months - 1 year)	27

Ref.	Common Name	Variety	Location	Protected	Maturity	No. Stems	Life Expectancy	Height	Crown width (m)	Structural Condition	Biological Condition	Pathogen Significance	Consequence of Whole tree failure	Inspect Period	Survey Notes	Size of Part	Likelihood of impact	Tree Failure Potential	Probability
T033	Wellingtonia		In grassed area between footway and cycleway	N/A	Semi Mature	1	EL (40+ Years)	15	5	Good	Good	None Present	Major	2 Years	Adequate clearance over footpath	None	Not Assessed	Not Assessed	
T034	Wellingtonia		In grassed area between footway and cycleway	N/A	Semi Mature	1	EL (40+ Years)	15	5	Good	Good	None Present	Major	2 Years	Adequate clearance over footpath, bat box on main stem.	None	Not Assessed	Not Assessed	
T035	Lombardy poplar		In grassed area between footway and cycleway	N/A	Mature	3	EL (40+ Years)	21	5	Good	Good	None Present	Major	2 Years		None	Not Assessed	Not Assessed	
T036	Lombardy poplar		In grassed area between footway and cycleway	N/A	Mature	3	EL (40+ Years)	21	5	Good	Good	None Present	Major	2 Years		None	Not Assessed	Not Assessed	
T037	Lombardy poplar		In grassed area between footway and cycleway	N/A	Mature	3	EL (40+ Years)	21	5	Good	Good	None Present	Major	2 Years		None	Not Assessed	Not Assessed	
T038	Wellingtonia		In grassed area between footway and cyclewa, opposite path to play area	N/A	Semi Mature	1	EL (40+ Years)	10	5	Good	Good	None Present	Minor	2 Years	One sided crown from previous damage. Crown now growing well	None	Not Assessed	Not Assessed	
T039	Lombardy poplar		In grassed area between footway and cycleway, almost opposite footpath to play area.	N/A	Mature	4	EL (40+ Years)	21	5	Good	Good	None Present	Major	2 Years		None	Not Assessed	Not Assessed	
T040	Scots pine		In grassed area between footway and cycleway	N/A	Young	1	L (21-40 Years)	10	5	Good	Good	None Present	Minor	2 Years	Tree has a lean towards the path but appears to have stabilised	None	Not Assessed	Not Assessed	
T041	Wellingtonia		In grassed area between footway and cycleway	N/A	Semi Mature	1	EL (40+ Years)	10	5	Good	Good	None Present	Major	2 Years	Relatively stunted tree, branch low over footpath.	None	Not Assessed	Not Assessed	
T042	Lombardy poplar		In grassed area between footway and cycleway	N/A	Mature	3	EL (40+ Years)	21	5	Good	Good	None Present	Major	2 Years		None	Not Assessed	Not Assessed	
T043	Scots pine		In grassed area between footway and cycleway	N/A	Young	1	M (10-20 Years)	5	5	Fair	Good	None Present	Minor	2 Years	Has lean and a restricting support post. Tree is unlikely to be stable	None	Not Assessed	Not Assessed	
T044	Scots pine		In grassed area between footway and cycleway	N/A	Young	1	EL (40+ Years)	10	5	Good	Good	None Present	Minor	2 Years	Established tree	None	Not Assessed	Not Assessed	
T045	Wellingtonia		In grassed area between footway and cycleway	N/A	Semi Mature	1	EL (40+ Years)	10	5	Good	Good	None Present	Moderate	2 Years	Feature tree	None	Not Assessed	Not Assessed	
T046	Pedunculate oak		Edge of grassed area by footpath, bin and car park.	N/A	Semi Mature	1	EL (40+ Years)	10	5	Good	Good	None Present	Moderate	2 Years	Recently excessively crown lifted approximately 4m all around.	None	Not Assessed	Not Assessed	
G047	Field maple Horse chestnut		Next to ramp for bridge	N/A	Mature	2	L (21-40 Years)	10	10	Fair	Good	Minor Fungal/ Pathogen Infection	Moderate	2 Years	Both trees have stems heavily covered in ivy	None	Not Assessed	Not Assessed	
G048	Weeping willow x2		Two close growing trees between footpath and river	N/A	Mature	2	L (21-40 Years)	10	10	Fair	Good	None Present	Moderate	2 Years		None	Not Assessed	Not Assessed	

Ref.	Common Name	Variety	Location	Protected	Maturity	No. Stems	Life Expectancy	Height	Crown width (m)	Structural Condition	Biological Condition	Pathogen Significance	Consequence of Whole tree failure	Inspect Period	Survey Notes	Size of Part	Likelihood of impact	Tree Failure Potential	Probability
T049	Crack willow		On edge of river.	N/A	Over Mature	1	L (21-40 Years)	15	15	Poor	Good	None Present	Moderate	2 Years	Tree previously pollarded, regrowth is now beginning to subside over the river. Repollarding is required otherwise stems will fail into the river. Ivy covers main stem inhibiting inspection.	Medium (150-450mm)	Minor	Likely (3+ months - 1 year)	12
T050	Crack willow		On river bank	N/A	Mature	1	M (10-20 Years)	15	15	Fair	Good	None Present	Minor	2 Years	Previous large stem failure at 2.5m. Some partly collapsed limbs, but generally tree seems reasonable given species.	None	Not Assessed	Not Assessed	
G051	Crack willow x5		Edge of grassed area next to river	N/A	Semi Mature	5	M (10-20 Years)	5	10	Fair	Good	None Present	Minor	2 Years	Sprawling group, no access underneath	None	Not Assessed	Not Assessed	
T052	Crack willow		On river bank	N/A	Mature	1	M (10-20 Years)	15	15	Good	Good	None Present	Minor	2 Years	Malformed tree with much of crown growing over grassed area. Significant limbs over the river consideration must be made to start a scheme of pollarding.	None	Not Assessed	Not Assessed	
G053	Hazel Common hawthorn Pedunculate oak		Centre of grassed area	N/A	Semi Mature	3	EL (40+ Years)	10	10	Fair	Good	None Present	Moderate	2 Years	Limited access underneath some of the group. Oak tree has numerous stems from 1m.	None	Not Assessed	Not Assessed	
T054	Crack willow		Next to the river	N/A	Mature	5	M (10-20 Years)	20	10	Poor	Good	Significant Fungal/ Pathogen Infection	Moderate	2 Years	One stem is clearly subsiding over the grassed area. Branch torn in the crown over rough area. One stem has Phellinus fungal fruiting bodies at 1.5m & 3m. Tree is becoming increasingly vulnerable to major failure	Medium (150-450mm)	Minor	Likely (3+ months - 1 year)	12
G055	Crack willow x10		Spread out group around boggy pond area	N/A	Mature	10	L (21-40 Years)	21	10	Fair	Good	None Present	Moderate	2 Years	Drawn up trees, likely to require height reduction or pollarding in the future. One tree split in half recently leaving one half standing, but biased into pond area.	None	Not Assessed	Not Assessed	

Ref.	Common Name	Variety	Location	Protected	Maturity	No. Stems	Life Expectancy	Height	Crown width (m)	Structural Condition	Biological Condition	Pathogen Significance	Consequence of Whole tree failure	Inspect Period	Survey Notes	Size of Part	Likelihood of impact	Tree Failure Potential	Probability
G056	Crack willow x7		On riverbank	N/A	Mature	7	L (21-40 Years)	20	5	Poor	Good	None Present	Moderate	2 Years	2 stems have been pollarded at 6m. One stem over the river has spilt with half falling into the river. Nearby Willow has been pollarded at 6m, the stems in this tree are becoming increasingly vulnerable to failure and the remainder should pollarded at a similar height as the adjacent trees.	Medium (150-450mm)	Moderate	Possible (1-5 years)	12
T057	Crack willow		On riverbank	N/A	Mature	1	L (21-40 Years)	10	5	Fair	Good	None Present	Minor	2 Years	Previously pollarded at 6m, strong regrowth is forming	None	Not Assessed	Not Assessed	
T058	Common alder		On riverbank	N/A	Mature	5	L (21-40 Years)	10	5	Good	Good	None Present	Minor	2 Years		None	Not Assessed	Not Assessed	
G059	Crack willow x5		Close to and on river bank towards drainage ditch.	N/A	Mature	5	L (21-40 Years)	21	15	Good	Good	None Present	Minor	2 Years	Three large stems leaning out over the river, one more severely than the others. Other adjacent stems have failed in recent years. A succession of pollarding will have to be considered soon to prevent tree failure.	None	Not Assessed	Not Assessed	
G060	Crack willow x2		Far end of site, next to drainage ditch	N/A	Mature	2	L (21-40 Years)	15	10	Good	Good	None Present	Minor	2 Years	Low levels of access nearby	None	Not Assessed	Not Assessed	
G061	Pedunculate oak x3		Three close growing trees towards far end of site near drainage ditch	N/A	Semi Mature	3	EL (40+ Years)	15	10	Fair	Good	None Present	Moderate	2 Years	All has upright biased forms and tight stem unions that appear stable	None	Not Assessed	Not Assessed	
G062	Poplar Cherry Common hawthorn Scots pine Common ash		Long group alongside former Wakeman playing fields	N/A	Mature	5	L (21-40 Years)	20	10	Fair	Good	None Present	Moderate	2 Years	Many trees heavily covered in ivy.	None	Not Assessed	Not Assessed	